

To: Wharton, Steve[Wharton.Steve@epa.gov]
From: Jenkins, Joy
Sent: Fri 8/14/2015 5:42:58 PM
Subject: FW: cjack water pool

Please see below for correspondence with the design team for Captain Jack -- read Craig's email first, then mine. I think we'll need to have some discussions on this and see if there is additional information that can be gathered from the site.

Thanks – Joy

Joy Jenkins

Remedial Project Manager

EPA Region 8

Phone: 303-312-6873

Travel/remote work phone: 720-951-0793

From: Jenkins, Joy
Sent: Friday, August 14, 2015 11:41 AM
To: 'Weber, Craig L'; Boardman - CDPHE, Mary
Cc: Ivancie, Paul
Subject: RE: cjack water pool

Thanks Craig,

Nonresponsive

Nonresponsive

I also don't have all the facts from the OSC's that were working on the Gold King yet, So the following information is not official and should only be viewed by our Captain Jack Team:

My understanding is that the American Tunnel was plugged many years ago (around 2002?) and the Red and Bonita have not yet been plugged. Removal program work was underway toward that effort but no plugs have been installed yet in the Red and Bonita (this part I am certain of). The Gold King has run AMD water for many years at anywhere between 75 and 300 gpm. So this system was also not completely blocked. Thus the reason that the removal program was trying to assess the collapsed Gold King was to determine what could be done to stop or control the flows from it. So as far as I understand there had been no recent human activity that would have caused additional water/pressure to back up into the Gold King.

Nonresponsive

Nonresponsive

Nonresponsive

Thanks - Joy

Joy Jenkins

Remedial Project Manager

EPA Region 8

Phone: 303-312-6873

Travel/remote work phone: 720-951-0793

From: Weber, Craig L [mailto:craig.weber@amecfw.com]

Sent: Friday, August 14, 2015 9:50 AM

To: Boardman - CDPHE, Mary

Cc: Jenkins, Joy; Ivancie, Paul

Subject: cjack water pool

Mary;

Nonresponsive

We're only hearing bits and pieces of the situation at Gold King – but from what we gather, there appears to have been a significant buildup and increase in the water flow within the Gold King mine, possibly due to historical work at the American Tunnel and recent work at Red and Bonita.

Nonresponsive

Nonresponsive

Craig L. Weber, P.E.

Principal, Unit Manager Denver, Amec Foster Wheeler

2000 S. Colorado Blvd., Suite 2-1000, Denver, CO 80222, USA

T +1 303 630 0771 M +1 303 549 7834
craig.weber@amecfw.com amecfw.com



This message is the property of Amec Foster Wheeler plc and/or its subsidiaries and/or affiliates and is intended only for the named recipient(s). Its contents (including any attachments) may be confidential, legally privileged or otherwise protected from disclosure by law. Unauthorised use, copying, distribution or disclosure of any of it may be unlawful and is strictly prohibited. We assume no responsibility to persons other than the intended named recipient(s) and do not accept liability for any errors or omissions which are a result of email transmission. If you have received this message in error, please notify us immediately by reply email to the sender and confirm that the original message and any attachments and copies have been destroyed and deleted from your system. This disclaimer applies to any and all messages originating from us and set out above. If you do not wish to receive future unsolicited commercial electronic messages from us, **please forward this email to: unsubscribe@amecfw.com and include "Unsubscribe" in the subject line.** If applicable, you will continue to receive invoices, project communications and similar factual, non-commercial electronic communications.

Please click <http://amecfw.com/email-disclaimer> for notices and company information in relation to emails originating in the UK, Italy or France.